



Service Bulletin

- Issue of recall:** Faria Depth Sounders, produced in late 2013 through early 2014 will not function and display “0.0” after only a couple power-on, power-off cycles.
- Subject:** Faria is offering a replacement instrument to customers experiencing Depth Sounders that fail to function properly after only a couple of power-on/power-off activities.
- Notice:** Depth Sounders installed may experience failure after only a couple of power-on, power-off cycles. ***With the boat in the water*** and power on the display blinks “0.0” and will not display accurate depth.
- Resolution:** Faria is aware of the problem and has corrected the issue. If you are experiencing this failure, contact Faria Customer Service. A new Depth Sounder will be provided to replace the non-functional unit.
- In addition, Depth Sounders manufactured during this period are warrantied for 3 years.
- For additional information or you have any questions regarding this, please call Faria Customer Service at 1-800-473-2742 for assistance.
- Important:** Depth Sounders with Dual Temperature (Air and Water Temperature) are not affected by this bulletin.