

Harness HN0325 4 - pin connector Pilot w/ Ballast

Harness HN0326 6 - pin connector Pilot w/ Ballast

4- pin connector (CN0082)

Pin A	Red	+12 vDC Battery
Pin B	Black	Ground
Pin C	Black/White	Transducer Ground
Pin D	Blue	Depth Sounder signal

ECR0249 8/30/00

6- pin connector (CN0083)

Pin A	Plug	Not used
Pin B	Plug	Not used
Pin C	Plug	Not used
Pin D	White	Water Temperature
Pin E	White/Red	Ballast
Pin F	Green	Speedo Sensor

ECR 0037 6/13/00

